


90072 Service Kit

Seal Replacement 880-343 & 880-345



*Note: Valves with an air supply port marked "INLET", use o-ring 11003-27 (item 4).
Valves with an air supply port marked "IN", use o-ring 11003-26 (item 5).

The illustration above shows model 880-343-01. Seal placement is the same for model 880-345-01.

#	Part #	Item Description	Qty.
1	11034-03	Seal ring - square cut	1
2	11003-16	O-ring (requires o-ring lube)	1
3	11361-02	Cup seal - piston (requires o-ring lube)	1
4*	11003-27	O-ring (requires o-ring lube)	1
5*	11003-26	O-ring	2
6	11039-13	O-ring	1
7	11003-20	O-ring (requires o-ring lube)	1



Franklin Fueling Systems

3760 Marsh Road • Madison, WI 53718 U.S.A.

Tel: +1 608 838 8786 • Fax: +1 608 838 6433 • www.franklinfueling.com

Tel: USA & Canada 1 800 225 9787 • Tel: Mexico 001 800 738 7610

